Resident witnesses:

***************************************	 	••••••	

 T33N,	R 10E	
' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' '	, , , , , , , , , , , , , , , , , , , ,	
! !		
 Sect.	26 	
 	i I :	l I
 	 	 -
 	; ; [)
		I

O = Corner monument restored.

CERTIFIED LAND CORNER RESTORATION

Index No. T-19

History of original corner establishment:

DRIGINAL CORNER NOT ESTABLISHED DURING ORIGINAL GOV'T SURVEY.


Description of corner evidence found:

FOUND I" IRON PIPE AND LOCATION TAG

ON ASPEN REPLACED IP WITH 2" & 42"

BLACK IRON PIPE WITH BRASS CAP MON

SCRIBED 3 NEW BT'S.



William J. Kelly

Description of monument and accessories I established to perpetuate the original location of this corner.

PK & RIBEON 19/10 SET IN "X" MONUMENT 4. 23. 82 10" ASPEN WITH RUSTED	4	ALL BT'S NEW . 7º M) KEPLACED	6" MAPLE	CENT SECT . SECT 26
PK & RIBEON 10" ASPEN WITH RUSTED	X		540.	- 2"x 42' BRASS CAP MONUMENT	-
	NORT	PK & RIBEON SET IN "X"	2) 10		

Dated at ELCHO	, Wis., this	2320	day ofMA	RCH , 19 82
Signature William d. 1-	Title	COUNTY	SURVEYOR	Registration No. 1098
(County Surveyor,) Office of Register of Deeds, Coun	Registered Land Survey			I hereby certify that the within
nstrument was filed in this office	for record on the		day of	, 19
ato'clock				
				•

(Register of Deeds)