PUBLIC LAND SURVEY MONUMENT RECORD U.S.

INSTRUCTIONS:


This record shall show the location of the corner and shall include all of the following nine elements (a through 1).

(a) Identify the corner by reference to the U.S. public land survey system.

O = Corner monument restored

Northwest Corner Section 35


This corner was originally set by Hiram C Fellows in 1860. The GLO completed a re-survey of this area in the 1930's setting a 1 1/2" Capped pipe.



Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material (b) evidence you considered, and whether the monument was found or placed.

We found a 1 1/2" capped iron pipe standing next to a 3" x 3" squared cedar post.

In the plan view drawing below, provide reference ties to at least 4 witness monuments, or, if the location is within a (c) municipality, to at least 2 witness monuments. (Witness monuments shall be made of concrete, natural stone, iron or other equally durable material.)



Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

N/A

(f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location.?

Z) I FEEL A GOOD CHAIN OF RECORD IS

ASSOCIATED WITH THIS CORNER

(g & h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location.

(i) I, DAN HIGGINBOTHAM

5-1935

(type or print name)

certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Signature Diggin Softe

2-6-95

Affix Land Surveyor Seal

DANIEL E. HIGGINBOTHAM S-1935 BIRNAMWOOD,

SURV

Date