CERTIFIED LAND CORNER RESTORATION

Index No. T-13

State of Wisconsin
County of LANGLADE } ss.

I WILLIAM F. KELLY, do hereby certify that on the 24TH day of MARCH, 19 76, I found evidence of the 1/4 SECTION corner of SECTIONS 28 & 27 Township 33, North, Range 10E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

R. HESS, SR.

T. 33 N.-R. 10E.



O = Corner monument restored.

History of original corner establishment:

WISCONSIN
WILLIAM F. KELLY
S1098
ELCHO, WIS.
LAND SURVEYOR

William F. Kelly

Description of corner evidence found:
4" PIPE WITH GALVANIZED CAP SCRIBED 1/4.
IDENTIFIED BY RESIDENT WITNESS AS THE 1/4 CORNER OF SECTIONS 28 & 27.

MONUMENT REPORTED AS MISSING 6/94 BY MR. MISHLER
11/00 RICHARD ZACHARIAS SAYS MONUMENT IS STILL THERE

Description of monument and accessories I established to perpetuate the original location of this corner.



MARKED AND SCRIBED WITNESS TREES.

Dated at ELCHO, Wis., this 24TH day of MARCH, 19 77

Signature William F. Kelly Title REGISTERED LAND SURVEYOR Registration No. S1098
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of ....., I hereby certify that the within instrument was filed in this office for record on the ..... day of ....., 19.....
at ..... o'clock ..... M.

.....
(Register of Deeds)

By ..... Deputy

FORM 985 H. C. MILLER CO., MILWAUKEE