Resident witnesses:

ROBERT	HESS, S	R
		•••••

T. 33 N R. 10 E .			
			1
1	1	· 	1
	l .	1	l
	 	¦	
1	1] I	1 1
	1	I	1
	\\ 2	8	<u> </u>
	1	i	
	1	l I	i 1
	 	!	<u> </u>
	I	i	1
	1	i	
}	1	I I	! !

O = Corner monument restored.

CERTIFIED LAND CORNER RESTORATION

Index No. T-9

History of original corner establishment:

ORIGINAL CORNER SET BY HIRAM FELLOWS IN OCTOBER 1860.

CORNER IDENTIFIED BY GENISOT ENGINEERING OF RHINELANDER IN THE 1950'S.

Description of corner evidence found:

LOCATED 4x 4 POST ON GROUND. EXCAVATED AT BASE OF POST AND FOUND POINT OF POST INTACT. FOUND ONE OLD BEARING TREE, POST LOCATION IDENTIFIED BY RESIDENT WITNESS AS 1/4 CORNER.

Description of monument and accessories I established to SET 2" BRASS CAP AND MARKED IN 12"MARKED TREES MARKED P.K. NAIL B' MAPLE	7/14 G
Dated at ELCHO , Wis., this	3 RO day of MARCH , 1980
Signature William & Velly Title Co	
Office of Register of Deeds, County ofinstrument was filed in this office for record on the	day of
ato'clock M.	WILLIAM F. KELLY S1098
(Register of Deeds)	ELCHO, WIS.
Ву	