of FEBRUARY 1980, I found evidence of the N'/8 corner of SECTION 32 33

Resident witnesses:

 	<i>-</i>	 

T. 33N. -R. 10 E.

O = Corner monument restored.

## CERTIFIED LAND CORNER RESTORATION

Index No. W - 9

History of original corner establishment:

ORIGINAL CORNER SET HIRAM FELLOWS IN OCTOBER 1860.

Description of corner evidence found:

LOCATED 4 × 4 CEDAR POST AND 3 EXISTING BEARING TREES CALLED FOR IN RAY HALLISEYS NOTES.



Description of monument and accessories I established to per SET 1/2" × 42" BLACK IRON PIPE WITH BRASS SET 4 × 4 POST NORTH OF MONUMENT AS CORNER IS IN A BLACK ASH, SPLUCE, CEDAR	CAP. REMARKED BEAR. A WITWESS POST.	of this corner.  NYB COP.  SECT
The same of the sa	Y 42" IRON PIPE WITH BRASS CAP	32 33 T33 N R 10 E
+ P.K. NAIL 6"BLACK ATH WAS	O6" BLACK AFH	3-18-80 W.F.K.
Dated at	day of	
Signature Wellam S. Kelle Title COUNTY (County Surveyor, Registered Land Surveyor, or other	SORUEYOR her duly authorized official)	Registration No. 5/098
Office of Register of Deeds, County of	, I h	ereby certify that the within, 19
(Register of Deeds)		