<b>¬</b>	:	7	16160	IVVID	CODNICD	RESTORATION	
٠,	- 1	<b>イ</b> I	151517	I AIVI	CURNER	RESTURATION	

Index No. A.23

History of original corner establishment:

I Raymond J. Hallisy , do hereby certify that on the 3rd day of June , 19.78 , I found evidence of the Section 36 & 1 corner of 32 & 33

Township XXXX 10E , North, Range , Fourth Principal Meridian,

SS.

State of Wisconsin

County of Langlade

as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

132NRIOE | Section 36 | Section 36 | Section 1

O = Corner monument restored.

Description of corner evidence found:

at o'clock M.

4" Galvanized pipe with cap, almost flush with the ground.

Description of monument and accessories I established to perpetuate the original location of this corner.

Mew BT's

 (14)

Dated at Antigo , Wis., this 3rd day of June , 19.78

Signature Allily Title Land Surveyor Registration No. S-685

(County Surveyor, Registered Land Surveyor, or other duly authorized official)

(Register of Deeds)

By.....Deputy