

CERTIFIED LAND CORNER RESTORATION

Index No. E-21

State of Wisconsin }
County of Langlade } ss.

I Raymond J. Hallisy, do hereby certify that on the 6th day of May, 1979, I found evidence of the Section corner of Section 1, 2, 11, & 12 Township 33, North, Range 11E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

History of original corner establishment:

Corner set in the 1930 resurvey.

Description of corner evidence found:

4" pipe with brass cap.

Resident witnesses:



.....
.....
.....

Description of monument and accessories I established to perpetuate the original location of this corner.

New BT's

7"	Hard Maple	N14W	31' 7"
4"	Red Maple	S3E	21' 3"
4"	Red Maple	S5W	14' 1"
3"	Red Maple	S78W	15'

Rock Mound



○ = Corner monument restored.

Dated at Antigo, Wis., this 6th day of May, 1979

Signature Raymond J. Hallisy Title Peg. Surveyor Registration No. S-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19..... at..... o'clock..... M.

.....
(Register of Deeds)

By..... Deputy

FORM 985 H. C. MILLER CO., MILWAUKEE