

CERTIFIED LAND CORNER RESTORATION

Index No. E-19

State of Wisconsin }
County of Langlade } ss.

I, Raymond Hallisy, do hereby certify that on the 20th day of June, 1987, I found evidence of the N 1/4 corner of Section 11 Township 33, North, Range 11 E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

.....
.....
.....

History of original corner establishment:

CORNER ESTABLISHED IN 1980 RESURVEY

Description of corner evidence found:

4" IRON PIPE WITH BRASS CAP




Description of monument and accessories I established to perpetuate the original location of this corner.

New BT, S

<u>Hard maple</u>	<u>10"</u>	<u>55°E</u>	<u>38'6"</u>
" "	<u>7"</u>	<u>58°E</u>	<u>40'7"</u>
<u>Cherry</u>	<u>9"</u>	<u>N85°E</u>	<u>9'2"</u>
<u>Hard maple</u>	<u>9"</u>	<u>S24°E</u>	<u>24'3"</u>

T33N R11E



○ = Corner monument restored.

Dated at Antigo, Wis., this 20th day of June, 1987.

Signature Raymond Hallisy Title Land Surveyor Registration No. S-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy

FORM 985 K. C. MILLER CO., MILWAUKEE