

CERTIFIED LAND CORNER RESTORATION

33-11

Index No. E-16


State of Wisconsin }
County of Langlade } ss.

I, Raymond J. Hallisy, do hereby
certify that on the 3rd day
of May, 1970, I found
evidence of the E 1/16
corner of Section 3
Township 33, North, Range
11E, Fourth, Principal Meridian,
as described hereon; and that from this evidence
I established a new monument and accessories
as described hereon to perpetuate the original
location of this corner.

Resident witnesses:

J. Weir
J. Kriska

FORM 985 H. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

History of original corner establishment:


Corner set in the 1930 resurvey.

Description of corner evidence found:

Found old stake down point in ground, large rock mound
Stake marked 1/8 3 10

Description of monument and accessories I established to perpetuate the original location of this corner.

Set 2" pipe with brass cap large rock mound.
New B.T.'s
Hard maple 4" N57E 25 Ft. 9 inches
Basswood 8" S20W 5 Ft. 5 inches
B.T.'s faced at base of tree and scribed BT.



Dated at Antigo, Wis., this 3rd day of May, 1970

Signature Raymond J. Hallisy Title Reg. Land Surveyor Registration No. S-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within
instrument was filed in this office for record on the _____ day of _____, 19____
at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy