

CERTIFIED LAND CORNER RESTORATION

Index No. E-15


State of Wisconsin }  
County of Langlade } ss.

I Raymond J. Hallisy, do hereby certify that on the 20th day of August, 1977, I found evidence of the 1/4 corner of Section 3 & 10 Township 33, North, Range 11E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

.....  
.....  
.....

FORM 985 H C MILLER CO., MILWAUKEE



○ = Corner monument restored.

History of original corner establishment:

Corner set in the 1930 resurvey


Description of corner evidence found:

4" iron pipe with brass cap

Description of monument and accessories I established to perpetuate the original location of this corner.

B T's

- 8" White Ash N89W 29.9 Feet
- 7" Hard Maple N15E 5 Feet
- 10" Hard Maple S53E 36.6 Feet



Dated at Antigo, Wis., this 20th day of August, 1977.

Signature Raymond J. Hallisy Title Land Surveyor Registration No. S685  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of \_\_\_\_\_, I hereby certify that the within instrument was filed in this office for record on the \_\_\_\_\_ day of \_\_\_\_\_, 19\_\_\_\_ at \_\_\_\_\_ o'clock \_\_\_\_\_ M.

.....  
(Register of Deeds)

By.....Deputy