

CERTIFIED LAND CORNER RESTORATION

Index No. D-17

State of Wisconsin }
County of Lancaster } ss.

History of original corner establishment:

33-11

I Raymond J. Hallisy, do hereby certify that on the 6th day of May, 19 79, I found evidence of the S 1/16 corner of Section 2 & 3 Township 33, North, Range 11E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Corner set in the 1930 resurvey.

Description of corner evidence found:

Wood post down, marks gone, rock mound.


Resident witnesses:

.....
.....
.....


Description of monument and accessories I established to perpetuate the original location of this corner.

Set 2" pipe with brass cap, rock mound.
New BT's

6" Hard Maple N18E 26' 6"
4" Hard Maple S49E 12' 6"
4" Hard Maple S23E 9' 2"



FORM 985 H. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

Dated at Antigo, Wis., this 6th day of May, 19 79.

Signature Raymond J. Hallisy Title Reg. Surveyor Registration No. S-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of Antigo, I hereby certify that the within instrument was filed in this office for record on the 6th day of May, 19 79 at 10 o'clock AM.

.....
(Register of Deeds)

By..... Deputy