
U. S. PUBLIC LAND SURVEY MONUMENT RECORD

INSTRUCTIONS:

This record shall show the location of the corner and shall include all of the following nine elements (a through i).

- (a) Identify the corner by reference to the U.S. public land survey system.
 - O = Corner monument restored.



- (b) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.
 - 1. RESTORED MAY 11, 1969 TOWNSHIP INDEX NO.E-8
 - 2. WOODPOST- POINT ONLY
 - 3. 2" IRON PIPE WITH BRASS CAP FROST HEAVE-WOOD POST IN PLACE
 - 4. B.T.'s COT
 - 5 NEW B.T.S SCRIBED AT BASE OF TREES.
- (c) In the plan view drawing below, provide reference ties to at least 4 witness monuments, or, if the location is within a municipality, to at least 2 witness monuments. (Witness monuments shall be made of concrete, natural stone, iron or other equally durable material.) Describe witness monuments.
- (d) Show a plan view drawing depicting the relevant monuments and reference ties which is sufficient in detail to enable accurate relocation of the corner monument if the corner monument is disturbed. Indicate north.

ON NORTH SIDE CO. HWY T

W.C. SEC 5 - E/16

COR 1/2 RODS /

SOUTH

3- NEW BTS - BEARING TREES (B.T) TO WITNESS CORNER !) RED MAPLE - 12" - N4°E - 35.66 FEET 2) WH. BIRCH - 16" - N62°E - 83.83 FEET 3) HARD MAPLE - 12" - N70°W-73.33 FEET

REMOVE OLD CERTIFIED

CORNER SHEET - E-8

7 33N RIE

7

(e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

N. A. Comments

Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location? (f)

2

· Congression

(g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?

N. A.

(Lype or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record Is correct and complete to the best of my knowledge and belief.

Signature

5-3-91

Land Surveyor Seal \$**-**00685 ANTIGO WIS. SURY

Sta	ite of V	Viscon	sin	١
County o	f Langl	ade		ss.
	mond J. at on the.			
of M	at on the Iav		. 19 6	
evidence	lay of the	E 1/16		
corner of.	Sect	ion 8		
	33			
	ed hereon			
I establis	hed a new	v monum	ent and	accessorie
	bed hereor		oetuate	the origin
location	of this corn	ier.		
Resident	witnesses:			
•••••			•••••	
•••••				
)
	1	ì		
	1	1	ŀ	
	l I	l I	l I	
		¦	†	
		l	1	
	1	 	1	

			<u> </u>
		1	P .
		1	ا ا
1	ŀ	Į.	l .
,	1	1	ı
'			<u>'</u>
		¦	
	1	!	I
1			
	I	I	
	l _	1_	1
	5 <i>EC_</i> _	&	L
ı		1	'
		l .	1
1		i	ı
	1	I	I
'			
		¦	
	ı		
		!	<u>'</u>
		l	I
	l	1	l
		I	1
	_5 <u>E</u> C	 	

O = Corner monument restored.

History of original corner establishment:

Corner set in the 1930 resurvey.

Description of corner evidence found:

Found old stake standing, marked 1/8 Cor $1\frac{1}{2}$ RDS S

Description of monument and accessories I established to perpetuate the original location of this corner.

Set 2" pipe with brass cap north of road as witness corner.

B.T.'s to witness corner

N28W 66Ft. 6 inches N6W 63Ft. 5 inches

B.T.'s faced at base of tree and scribed BT

(County Surveyor, Registered Land Surveyor, or other duly authorized official) (Register of Deeds)