U. S. PUBLIC LAND SURVEY MONUMENT RECORD

INSTRUCTIONS:


This record shall show the location of the corner and shall include all of the following nine elements (a through i).

(a) Identify the corner by reference to the U.S. public land survey system.

O = Corner monument restored.

DRIGINAL CORNER ESTABLISHED

BY HIRAM C. FELLOWS IN OUT, 1860.



(b) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.


EXISTING REFERENCE MONUMENT, 3" ALUMINUM MONUMENT SET IN CONCRETE & 1/4 CORNER MONUMENT, 4" GALVANIZED CAP MONUMENT, FOUND IN PLACE.

- (c) In the plan view drawing below, provide reference ties to at least 4 witness monuments, or, if the location is within a municipality, to at least 2 witness monuments. (Witness monuments shall be made of concrete, natural stone, iron or other equally durable material.)

 Describe witness monuments.
- (d) Show a plan view drawing depicting the relevant monuments and reference ties which is sufficient in detail to enable accurate relocation of the corner monument if the corner monument is disturbed, indicate north.

ALL BT'S
EXISTING

SEI PK NAIL
RISISON



(e)	Describe any material discrepancy between the location of the corner as restored or
	reestablished and the location of that corner as previously restored or reestablished
	by distance and direction. Show the discrepancy on the plan view drawing under (d).
	above. Show the distances between the corner as previously restored or reestablished
	and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness
	monuments shown on the drawing in (d), above.

NONE

(f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

(2)


(g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?

No

(i) I. WILLIAM F. KELLY
(Lype or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record Is correct and complete to the best of my knowledge and belief.

William J. Rell

12-21-63



County of	Langlade	} s:	S.
certify that of Dece evidence of corner of Township 11E as described I establishe as described location of		, 19.82 , North Principal Mat from this e	I found Range eridian, vidence essories
Resident wi	tnesses:		
	······		
			••••••
•••••	·····		••••••
	1		 -
	1 1	1 1	
		 -	
	See 410	ا ک س	
	1 1 33 N K	-	Ψ
}		1	
<u> </u>	<u> </u> 		
	l 	1	: :
		l 	
O = Corner	monument res	tored.	

State of Wisconsin

CERTIFIED LAND CORNER RESTORATION


Index No. C - 9

History of original corner establishment:

Corner set in the resurvey of 1930's

Description of corner evidence found:

لاً Galvanized pipe with cap, 2" orange plastic pipe 3أوا above ground 10" north of corner.



Description of monument and accessories I established to perpetuate the original location of this corner.

New BT's

11"	Ash	s65₩	1.6
5"	Basswood	N2E	12.1
7"	Hard Maple	NLLE	17.8
611	Hard Maple	S66E	10.31

Dated at/Antigo/	. Wis., this	4th	dav of	December	. 19 82
Signature Antigo (County Surveyor, Registered Office of Register of Deeds, County of	Title	Lan d	Surveyor	Ro	egistration No. S-685
(County\Surveyor, Registered	d Land Surveyo	or, or othe	r duly authorized o	official)	3
Office of Register of Deeds, County of			•••••	, I hereb	y certify that the within
nstrument was filed in this office for reco	rd on the	••••••	day	of	, 19
(Register of Deeds)	•••••		••••••		