U.S. PUBLIC LAND SURVEY MONUMENT RECORD


NOTE: This form is intended and designed to fulfill all requirements of Wisconsin Administrative Code, Chapter A-E 7.08 U.S. Public Land Survey Monument Record (3)(a)(b)(c)(d)(e)(f)(g)(h)(i) An additional sheet may be added if necessary to conform with said requirements.

(a) Corner location: Township 33 North

Range 11 East

Town of UPHAM

LANGLADE County, Wisconsin



(b)(f)(g)(h) Description of monument found at this corner and if it was accepted, state all evidence (material, testimonial, occupational, plats, records, other monuments) used as a basis for accepting. If not accepted or if nothing was found, state evidence used as basis for establishing location. If reestablished through lost corner proportionate methods, indicate all monuments, distances and directions used to establish. Indicate type of monument found or set and sign post.

1860 - CORNER SET BY HERMAN C. FELLOWS, SET WOOD POST

B.T.

SUGAR 12 N 43 E 10 LKS. HEMLOCK 8 S 70 W 25 LKS.

1936 - E.F. KOWALKE AND C.W. BORTH, FOUND

STONE IN ROADWAY B.T.'s

CHERRY 6" N 53 E 47'


HEMLOCK 16" S 52°30' E 71.6'

SET BRASS CAP W.C. 50 LKS. DUE SOUTH

1977 - RAYMOND J. HALLISY FOUND 4" BRASSCAP W.C. AND

SET B.T.'S TO WITNESS CORNER

(c)(d)(e) Plan view of corner with ties to at least 4 witness monuments. If in disagreement with previously established corner, show the distances between the two corners and also indicate the ties to the disputed corner.



(i) I, Dennis Roberts, Registered Land Surveyor *S-1863, hereby certify that the corner location on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Jafet 11-03-99 ensus 3 Signature



index No.

M W

-			
-			
ſ			

State of Wisconsin

Raymond J. Hallisy , do hereby

certify that on the day of , 19..., I found evidence of the corner of , North, Range , Fourth Principal Meridian, as described hereon; and that from this evidence

I established a new monument and accessories

as described hereon to perpetuate the original

M33N RIVE

O = Corner monument restored.

County of Langlade

location of this corner.

Resident witnesses:

SS.

CERTIFIED	I AND	CORNER	RESTORATION

Index No. E - 3

History of original corner establishment:

Corner set in the 1930 resurvey.


Description of corner evidence found:

4" iron pipe with brass cap set as witness corner 50 Links South of corner. Corner sets in Hiway "T".

Description of monument and accessories I established to perpetuate the original location of this corner.

PT's to witness corner.

	Red Oak	S50E	27	Feet
	Hard Maple	S13E	18.4	Feet
611	Hard Maple	S58W	20.5	Feet



Dated at Antiro	, Wis., this	20th day of	August	197.7
Signature (County Su	Wis., this	Land Surveyor vor, or other duly authorized o	Registr	ation No.S685
Office of Register of Deeds	County ofs office for record on the	day	, I hereby cer	tify that the within19
to'clock	M.			
I)	Register of Deeds)			
3v		Deputy		