as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

SECTION Z

O = Corner monument restored.

CERTIFIED LAND CORNER RESTORATION

39-// Index No. **E - 2**

History of original corner establishment:

COR SET IN 1930 RESURVEY

Description of corner evidence found:

RANTRANSITLINE BET. 14 COR & TO T33N-RIE TO SECTION COR 1,6,7,12. SET 16 NT 20.92 Chs WHICH WAS 1930 RESURVEY MENSUREMENTS

Description of monument and accessories I established to perpetuate the original location of this corner.

SET 1/2 TRON PIPE WITH BRASS CAP AS W.C. 50 LKS South

NEW BT, S TO W/C.

BASSWIOD 12" 518 E 18.7 LKS.

10"520W. 21,8, 4KS.

W.C. 7 /6 W.C. 70 W.C.

Dated at Autigo Wis, this 18th day of August 1973

gnature As Mund Sullety Title Fig. 10 No. 5-685 (County Surveyor, Registration No. 5-685)

(Register of Deeds)

By.....Deputy