

CERTIFIED LAND CORNER RESTORATION

33-11
Index No. J-14

State of Wisconsin }
County of Langlade } ss.

History of original corner establishment:

Corner set in the 1930 resurvey.

I, Raymond J. Hallisy, do hereby certify that on the 26th day of July, 1970, I found evidence of the W 1/16 corner of Section 15 Township 33, North, Range 11E, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Description of corner evidence found:

Found old stake standing, rock mound. Marked 1/8 10 15

Resident witnesses:

.....
.....
.....


Description of monument and accessories I established to perpetuate the original location of this corner.

Set 2" pipe with brass cap, rock mound.

NEW B.T.'S
HARD MAPLE 4" N58°E 12' 8"
HARD MAPLE 5" N73°E 14' 1"



B.T.'S FACED AT BASE OF TREE AND SCRIBED BT



Dated at Antigo, Wis., this 26th day of July, 1970

Signature Raymond J. Hallisy Title Reg. Land Surveyor Registration No. S-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of....., I hereby certify that the within instrument was filed in this office for record on the.....day of....., 19..... at.....o'clock..... M.

.....
(Register of Deeds)

By.....Deputy

○ = Corner monument restored.