CERTIFIED	LAND	CORNER	RESTORATION
CERTIFIED	LAND	CORINER	KESTOKATION

30	10			-	4
		Index	No.	P=1	,

CORNER

.

History of original corner establishment:

RESET IN 1937 By COUNTY RESURVEY PROJECT

Description of corner evidence found: MAR 24, 1966 - FOUND JCRIBGO 4" SQUARED POST WITH ROCK HOUND. RAN BLUE PAINT LINES NORTH, EAST AND SOUTH FROM CORNER FOR COUNTY TIMBER SALE. PAINTED ASPEN TREES FACING THE CORNER APRIL 18, 1969 - FOUND CORNER HOVED 521°W - 21LKS. CORRECTIVE MEASURES: CHAINED 50° 29'W - 19.97 CHAINS FROM N.W CORNER OF SEC 7- T33N RIZE FOOND ORIGINAL HOLE WITH POINT AND ROCK HOUND. PAINT LINES AND TREES (AS ABOVE) AGREE WITH 1966 FINDINGS OF THE CORNER SET CORNER AS BELOW Description of monument and accessories I established to perpetuate the original location of this corner. SET 2 WEN IRON PIPE WITH BRASS CAP - ROCK HOUND THUSG HEASURGS WERE MARKED INTERSING TO INSURG BEARING TRIES MARKED B.T. ASPEN 10" 516°E-121K CORRECT LOCATION OF THE

ASpen 7" N2°W 36.8 KK ASpen 8" 562°W 44.41K	
N/16 IRON PIPE 1/2" - WITNESS CORNER N90°W 50 LK	s
Dated at ANTIGO , Wis., this A day of JUNE	, 19 69
Signature Jaymond Jalling Title Jay Sand Surveyor Registration N (County Surveyor, Registered Land Surveyor, or other duly authorized official)	5-68
(County Surveyor, Registered Land Surveyor, or other duly authorized official)	
Three of Register of Deeds, County of, I hereby certify the	it the within
nstrument was filed in this office for record on theday of	, 19
to'clock M.	

ASPEN 11" 537°E 15.3 LK

ASPEN 9" N72°E 20.6 K

(Register of Deeds)

By......Deputy

State of Wisconsin

County of LANGLADE ss


I RAYMOND I HALLISY, do hereby certify that on the day of MACH 1966, I found evidence of the NICO North, Range Fourth, Principal Meridian, as described hereon; and that from this evidence

I established a new monument and accessories as described hereon to perpetuate the original

Resident witnesses:

location of this corner.

JERRY KRYKA GERALD WEIX



O = Corner monument restored.