

CERTIFIED LAND CORNER RESTORATION

331
Index No. M-235

State of Wisconsin }
County of Lancaster } ss.

History of original corner establishment:

Corner set in the 1930 resurvey

I Raymond I. Hallisy do hereby certify that on the 11th day of November, 1972, I found evidence of the S 1/4 corner of Sec 13 + 18 Township 33, North, Range 11 + 12 E, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Description of corner evidence found:

Wood Corner Standing in N. Edge of Swamp

Resident witnesses:

.....
.....
.....


Description of monument and accessories I established to perpetuate the original location of this corner.

Set 1 1/2" iron pipe with brass cap

New BT's
Spruce 4" N62W 7FT 11 in.
Spruce 4" S50E 13FT 11 in.



FORM 985 M. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

Dated at Antigo, Wis., this 11th day of November, 1972

Signature Raymond I. Hallisy Title L.S. Surveyor Registration No. 50065
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy