

CERTIFIED LAND CORNER RESTORATION


33-11
Index No. M-17

State of Wisconsin }
County of Langlade } ss.

I Raymond J. Hallisy do hereby
certify that on the 15th day
of November, 1969, I found
evidence of the S 1/16
corner of Section 15
Township 33, North, Range
11E, Fourth, Principal Meridian,
as described hereon; and that from this evidence
I established a new monument and accessories
as described hereon to perpetuate the original
location of this corner.

Resident witnesses:

.....
.....
.....



○ = Corner monument restored.

History of original corner establishment:

Corner set in the 1930 resurvey.


Description of corner evidence found:

Found old stake standing, Large rock mound, old fence to the south.
Marked 1/8 14, 15.

Description of monument and accessories I established to perpetuate the original location of this corner.

Set 2" pipe with brass cap, rock mound.

No B.T.'s set at this corner, corner set in a grass marsh.



Dated at Antigo, Wis., this 15th day of November, 1969

Signature Raymond J. Hallisy Title Reg. Land Surveyor Registration No. S-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within
instrument was filed in this office for record on the _____ day of _____, 19____
at _____ o'clock _____ M.

.....
(Register of Deeds)

By _____ Deputy

FORM 985 M. C. MILLER CO., MILWAUKEE