State of W	isconsin]
County of	Langlade	} ss.
I		
Resident witnesses:		
1	 	i i
	1	
13	setion 13	- + •
1	 	!
O = Corner monument restored.		

CERTIFIED LAND CORNER RESTORATION

Index No. L-17

History of original corner establishment:

Corner set in the 1930 resurvey.

Description of corner evidence found:

4" iron pipe with brass can

? " Stone with X 10'10" 18" Stone with X N69F 101

Description of monument and accessories I established to perpetuate the original location of this corner.

New BT's

15:1" White Birch 534F 17: Red Maple Ped Maple 2711"

, Wis, this 12th day of April 19.80. Dated at.....

Signature Lyngul Fill I Land Surveyor Registration No. S-685 (County Surveyor, Registered Land Surveyor, or other duly authorized official)

instrument was filed in this office for record on the _______day of _______, 19______

at......o'clock..... M.

(Register of Deeds)