

CERTIFIED LAND CORNER RESTORATION

33-11


Index No. M-13

State of Wisconsin }  
County of Langlade } ss.

I, Raymond J. Hallisy, do hereby certify that on the 26th day of July, 19 70, I found evidence of the S 1/16 corner of Section 16 Township 33, North, Range 11E, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:  
.....  
.....  
.....

FORM 985 R. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

History of original corner establishment:

Corner set in the 1930 resurvey.

Description of corner evidence found:


Found old stake standing, rock mound. Marked 1/8 15 16

Description of monument and accessories I established to perpetuate the original location of this corner.

Set 2" pipe with brass cap, rock mound.

New B.T.'s  
Ash 6" S57W 2 Ft. 2 Inches  
Ash 4" S73E 29 Ft. 1 Inch

B.T.'s faced at base of tree and scribed BT



Dated at Antigo, Wis., this 26th day of July, 19 70

Signature Raymond J. Hallisy Title Reg. Land Surveyor Registration No. S-685  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of....., I hereby certify that the within instrument was filed in this office for record on the.....day of....., 19..... at.....o'clock..... M.

.....  
(Register of Deeds)

By.....Deputy