U.S. PUBLIC LAND SURVEY MONUMENT RECORD (Prepared and as required by S. A-E 7.08 W Administrative Code)

The NORTH LINE server of Section	20 , T. <u>33</u> N., R. <u>//</u> E	. Langlade County W
Corner was: (check all that apply) Restored through acceptance of an obliterated evidence Restored through acceptance of a found perpetuate Determined to be lost and re—established through (Show bearings and distances to PLSS corners us Restored/recovered/reestablished in a location that established position. (Show difference in plan view	ence location. ed location. proportionate methods. sed for proportioning.) differs from a previously	., Languago county, wi
☐ Check here if additional information is shown on the Describe record evidence, recovered physical evidence, or	e reverse side of this form.	ial evidence and all other evidence
considered in the recovery/restoration of the corner. The original corner was established in 1860 by Hiram 29 lks., and a birch, 10", South, 30 lks. The 1936 rea 4" iron pipe with brass cap an marked the following surface, S63°W, 14'; + on granite rock, N55°W, 27' 28.3'. 09/19/96 David E. Tlusty found no evidence of based on distances from the SW and NE bearing ston but no + on it.	C. Fellows. Original bearing survey of the entire township bearing objects (BO): + on a dark grey sands of the 4" iron pipe with brass	g trees: hemlock, 16", North, o established this corner and set dark grey rock even with tone even with surface, N18°E, cap. Re-established the corner
Physical description of the monument set: Set a 1 1/2" x 36" iron pipe with 4" brass cap. Set we east-west fence line.	hite vinyl sign post 1' east of	corner. Corner falls in old
Describe the accessories used to perpetuate the location accessories found/set. Describe measuring point on bea	n of the corner. Include a plar pring trees. Show any topogra	n view drawing and indicate aphic features that would
Tree are measured to an aluminum nail in a low blaze BT bearings magnetic with hand compass.	on the side of the tree shows	
Pine BT has "Bearing Tree" sign nailed to it facing the	1	GEORETIC
8" W. BIRCH	M 1 13 - FOUND A36 3.0. 49 / "+" IN ROCK.	2
N89°55'30'W 1530.33' NW coe. 5EC 20 FND 1P 14.0' W 15.30' W 16.21' 45' W	1/4"/P FOUND 584*43'E 10.33'	1/19.72', N'/4 COR SEC 20 FOUND I.R.
FOUND 1936 BO "+" IN ROCK WEST NORTH	M.C I LINE SEC 20-33-11	
	SURVEYORS SEAL	The <u>WEST MEANDER</u> corner of Section <u>20</u>
	Lett 1 C C C	T. 33 N., R. 11 E. Langlade County, WI
n, David E. TLUSTY, certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.	DAVID E A STATE OF ANYTHING ANYTH ANYTHING ANYTH AN	No.
F 20 E 1 let 3/3/97	200000	
Signature Date	Salar Commence and the salar	<pre>= Location of corner</pre>

WISCONSIN ADMINISTRATIVE CODE

A-E 7.07 Monuments. The type and position of monuments to be set on any survey shall be determined by the nature of the survey, the permanency required, the nature of the terrain, the cadastral features involved, and the availability of material.

History: Cr. Register, February, 1987, No. 374, eff. 3-1-87

A-E 7.08 U.S. public land survey monument record.

- (1) WHEN MONUMENT RECORD REQUIRED. A U.S. public land survey monument shall be prepared and filed with the county surveyor's office as part of any land survey which includes or requires the perpetuation, restoration, reestablishment or use of a U.S. public land survey corner, and.
- (a) There is no U.S. public land survey monument record for the corner on file in the office of the county surveyor or the register of deeds for the county in which the corner is located; or,
- (b) The land surveyor who performs the survey accepts a location for the U.S. public land survey corner which differs from that shown on a U.S. public land survey monument record filed in the office of the county surveyor or register of deeds for the county in which the corner is located; or,
- (c) The witness ties or U.S. public land survey monument referenced in an existing U.S. public land survey monument record have been destroyed or disturbed.
- (2) FORM REQUIRED. A U.S. public land survey monument record shall be prepared on the board-approved form or on a form substantially the same as the board-approved form which includes all the elements required by this section. A form used for this purpose shall be entitled, "U.S. Public Land Survey Monument Record".

Note: A copy of the board-approved form is available from the Department of Regulation and Licensing, Bureau of Business and Design Professions, 1400 East Washington Avenue, P.O. Box 8935, Madison, Wisconsin 53708.

- (3) MONUMENT RECORD REQUIREMENTS. A U.S. public land survey monument record shall show the location of the corner and shall include all of the following elements:
- (a) The identity of the corner, as referenced to the U.S. public land survey system;
- (b) A description of any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence considered by the surveyor, and whether the monument was found or placed;
- (c) Reference ties to at least 4 witness monuments. Witness monuments shall be concrete, natural stone, iron, bearing trees or other equally durable material, except wood other than bearing trees;
- (d) A plan view drawing depicting the relevant monuments and reference uses which is sufficient in detail to enable accurate relocation of the corner monument if the corner monument is disturbed;
- (e) A description of any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished:
- (f) Whether the corner was restored through acceptance of an obliterated evidence location or a found perpetuated location;
- (g) Whether the corner was reestablished through lost-corner-proportionate methods;
- (h) The directions and distances to other public land survey corners which were used as evidence or used for proportioning in determining the corner location; and,
- (i) The stamp and signature or seal and signature of the land surveyor under whose direction and control the corner location was determined and a statement certifying that the U.S. public land survey monument record is correct and complete to the best of his or her knowledge and belief.

History: Cr. Register, February, 1987, No 374, eff. 3-1-87, am. (1) and (3) (c), Register, May, 1989, No 401, eff. 6-1-89