

CERTIFIED LAND CORNER RESTORATION

93-11
Index No. K-9

State of Wisconsin }
County of Langlade } ss.

History of original corner establishment:

Corner set in the 1930 resurvey.

I Raymond J. Hallisy do hereby certify that on the 15th day of November, 1969, I found evidence of the N 1/16 corner of Sections 16 & 17 Township T33, North, Range 11E, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Description of corner evidence found:



Found two old wooden posts, one on each side of old road.
The one on the east side of road marked 16 1/8 Cor 1 1/2 rds W.
The one on the west side of road marked 17 1/8 Cor 1 1/2 rds E.

Resident witnesses:

.....
.....
.....

Description of monument and accessories I established to perpetuate the original location of this corner.

Set 2" pipes with brass caps at locations of old W.C.'s.
B.T.'s to true corner.
12" Hemlock N72E 56 Lks.
12" White Pine S 61E
B.T.'s faced at base of tree and marked BT



Dated at Antigo, Wis., this 15th day of November, 1969

Signature: *Raymond J. Hallisy* Title: Reg. Land Surveyor Registration No. S-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

.....
(Register of Deeds)

By..... Deputy

○ = Corner monument restored.

FORM 985 M. C. MILLER CO., MILWAUKEE