State of Wisconsin

I WILLIAM F. KELLY, do hereby certify that on the 17th day of New , 19.80, I found evidence of the NW 11th corner of Sec. 19

County of LANGLADE

O = Corner monument restored.

CERTIFIED LAND CORNER RESTORATION

Index No. 0 - 2

History of original corner establishment:


NONE

SS.

Description of corner evidence found:

COPYER ESTABLISHED FROM CONTROL SUPVEY OF SECT 19 T33 N RIVE

(Register of Deeds)



SET 11/2" * 42" BLACK IRON PIPE WITH BRASS CAP MONUMENT
Description of monument and accessories I established to perpetuate the original location of this corner.

1			£	8" MAPLE	NW 1116 COR SEC 19	
¥		مريع و	38a·e	z" BRASS CAP-	733N + RIIE	E
Nonth	ALL BT'S NEW	IZ" MAPLE	- 0	14" YELLOW BIRCH	11-17-80 W F K	
Dated at	Есно	, Wis., this	175	day of	NOV	, 19 80
Signature.	Milliam &)	TitleTitle	COUNTY or, or other di	SURVEYOR uly authorized offic	Registratio	n No. 1098
nstrumen	Register of Deeds, County t was filed in this office fo	of/r record on the		day of.	, I hereby certify	that the withir
	.o clock					