

CERTIFIED LAND CORNER RESTORATION

33-11


Index No. Q-15

State of Wisconsin }
County of LANGLADE } ss.

I RAYMOND J. HALLISY, do hereby
certify that on the 19TH day
of MAY, 19 73, I found
evidence of the SOUTH CENTER 1/16
corner of SECTION 22
Township 33, North, Range
11 EAST, Fourth Principal Meridian,
as described hereon; and that from this evidence
I established a new monument and accessories
as described hereon to perpetuate the original
location of this corner.

Resident witnesses:

.....
.....
.....



○ = Corner monument restored.

History of original corner establishment:

SET BY RAMOND J. HALLISY
IN SUBDIVISION OF SOUTHEAST 1/4
OF SECTION 22.

Description of corner evidence found:

SQUARED CEDAR POST; ROCK MOUND
ROAD 2 FEET SOUTH RUNNING EAST & WEST

Description of monument and accessories I established to perpetuate the original location of this corner.

1 1/2" IRON PIPE WITH BRASS CAP
ROCK MOUND
NEW B.T.s
HARD MAPLE 8" N30E 36 FT 3 INCHS
HARD MAPLE 4" N46W 18 FT



Dated at ANTIGO, Wis., this 19TH day of MAY, 19 73.

Signature Raymond J. Hallisy Title Reg. Land Surveyor Registration No. 5-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of....., I hereby certify that the within
instrument was filed in this office for record on the.....day of....., 19.....
at.....o'clock..... M.

.....
(Register of Deeds)

By.....Deputy