

CERTIFIED LAND CORNER RESTORATION

33-11

Index No. V-22

State of Wisconsin }
County of Langlade } ss.

History of original corner establishment:

Corner set in the 1930 resurvey.

I Raymond J. Hallisy do hereby certify that on the 26th day of July, 19 70, I found evidence of the W 1/16 corner of Section 25 Township 33, North, Range 11E, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Description of corner evidence found:

Found old stake down, point in ground, rock mound
Marked 26 36 1/8

Resident witnesses:



.....
.....
.....

Description of monument and accessories I established to perpetuate the original location of this corner.

Set 2" pipe with brass cap, rock mound.

New B.T.'s

10" Aspen N72E 21 Ft. 7 Inches
8" Aspen S25W 16 Ft. 4 Inches
B.T.'s faced at base of tree and scribed BT.



○ = Corner monument restored.

Dated at Antigo, Wis., this 26th day of July, 19 70

Signature Raymond J. Hallisy Title Reg. Land Surveyor Registration No. S-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19 _____ at _____ o'clock _____ M.

.....
(Register of Deeds)

By _____ Deputy

FORM 985 H. C. MILLER CO., MILWAUKEE