

CERTIFIED LAND CORNER RESTORATION

Index No. V-21

State of Wisconsin }
County of Langlade } ss.

History of original corner establishment:

ESTABLISHED August 29th 1936
IN RESURVEY

I, Raymond J. Hallisy, do hereby certify that on the 28th day of August, 1976, I found evidence of the SECTION corner of 25, 26, 35, 36 Township 33, North, Range 11 EAST, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Description of corner evidence found:

4" IRON PIPE WITH BRASS CAP
Fence south & west



Resident witnesses:

.....
.....
.....

Description of monument and accessories I established to perpetuate the original location of this corner.

NEW B.T.S.

WHITE SPRUCE 9" 536W 55.5 Foot
" " 10" 568W 44.6 Foot



○ = Corner monument restored.

Dated at Antigo, Wis., this 28th day of August, 1976.

Signature Raymond J. Hallisy Title Registered Land Surveyor Registration No. 5685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

.....
(Register of Deeds)

By _____ Deputy