U.S. PUBLIC LAND SURVEY MONUMENT RECORD (Prepared and as required by S. A-E 7.08 W Administrative Code)

• • •	•	· · · · · · · · · · · · · · · · · · ·
The SOUTH QUARTER corner of S	ection <u>30</u> , T. <u>33</u> N., R. <u>//</u> E.,	Langlade County, WI
Corner was: (check all that apply) Restored through acceptance of an obliter Restored through acceptance of a found process of a found process of the corner of the corn	perpetuated location. through proportionate methods. corners used for proportioning.)	1120 0000 16 46
established position. (Show difference in	plan view below.)	1130 0020 1999
Check here if additional information is sho Describe record evidence, recovered physical ev	vidence, occupational evidence, testimonial	evidence and all other evidenc
considered in the recovery/restoration of the carrier was established in 1860 by	corner. v Hiram C. Fellows. Original bearing tre	es: hemlock, 12", S4°E,
7 links and a hemlock, 18", N34°W, 14 links.	B.F. Dorr, in 1891 (FB98-42) surveyed	the N-S ¼ line in Section
31, but didn't describe this corner. Webley, in corner and running south. The 1936 Kowalke of U.S.Hiway 45. Witnesses: Concrete posts centers of tops which are marked with an +. Brass cap in Hiway for true 1/4 cor. Set anoth	e and Borth resurvey of this township says 4 x 4 on top one E & one W of Hiway. 44 falls 17.05' S of a point midway between	Posts are 66.2' apart from een posts. Leaded one
Certified Survey Map 7-69 by Tom Arnott inc	dicates that this corner is a PK nail found	On 07/07/99 I found a
4" brass capped embedded in the old concrete cap as the best perpetuated evidence of the or	e pavement, 2.3' below the existing pave	ment. Accepted the brass
Physical description of the monument set:	•	
Set Berntsen SN-1 nail in road patch over brapavement.	ass cap found in old concrete road, down	2.3' below existing
Describe the accessories used to perpetuate t accessories found/set. Describe measuring pound in future recovery of the corner.	he location of the corner. Include a plan volint on bearing trees. Show any topograp	view drawing and indicate hic features that would
$0 = \frac{3}{4}$ " x 30" rebar set		Notes FB17-19
\odot = 4" iron pipe with brass cap found (1936		ı
Bearing based on magnetic compass reference Ties electronic with Geodimeter robotic total		
power pok - 5 8 2.5	iz iron	
power poe —	found power pole	1
\z	, , ,	
11 × 500 × 1		
12 miles 12 miles	\$\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	
2' \	000 m/ 10 /2 /2 /2 /2 /2 /2 /2 /2 /2 /2 /2 /2 /2	
concrete RW) T3.	END A Concrete R/W	
post value	10 / 16 116 1 16 1 1 1 1 1 1 1 1 1 1 1 1 1	
White viny sign post	5/4 CORNER 30.33-1	/
0.9± ~ N84°59'45 W	FOUND 4"BC IN old conce	ete paut.
32.95'	150	
22/0	3 3 6 5 F	The South QUARTER
5/2.7	SURVEYORS SEAL	corner of Section 30
60d 20 / set Nand CAR	(Na)	T 33 N R // F
FOUND	**************************************	Langlade County, W
DAVID E. TLUSTY	Harring CON STATE	Langlade County, W
I, <u>LANGLADE</u> <u>COUNTY SURVEYOR</u> , certify the corner location shown on this record was determined.	ermined SA DAVIDE ON STEEL	
by me or under my direction and control and U.S. Public Land Survey Monument Record is	that this TLUSTY correct S-1390 CG	30 T
and complete to the best of my knowledge a	nd belief. ANTIGO ANTIGO	
9 oliter - 1.1.	AND	
Signature Do	ite LAME	O = Location of corner

WISCONSIN ADMINISTRATIVE CODE

A-E 7.07 Monuments. The type and position of monuments to be set on any survey shall be determined by the nature of the survey, the permanency required, the nature of the terrain, the cadastral features involved, and the availability of material. History: Cr. Register, February, 1987, No. 374, eff. 3-1-87.

A-E 7.08 U.S. public land survey monument record.

- (1) WHEN MONUMENT RECORD REQUIRED. A U.S. public land survey monument shall be prepared and filed with the county surveyor's office as part of any land survey which includes or requires the perpetuation, restoration, reestablishment or use of a U.S. public land survey corner, and,
- (a) There is no U.S. public land survey monument record for the corner on file in the office of the county surveyor or the register of deeds for the county in which the corner is located; or,
- (b) The land surveyor who performs the survey accepts a location for the U.S. public land survey corner which differs from that shown on a U.S. public land survey monument record filed in the office of the county surveyor or register of deeds for the county in which the corner is located, or,
- (c) The witness ties or U.S. public land survey monument referenced in an existing U.S. public land survey monument record have been destroyed or disturbed.
- (2) FORM REQUIRED. A U.S. public land survey monument record shall be prepared on the board-approved form or on a form substantially the same as the board-approved form which includes all the elements required by this section. A form used for this purpose shall be entitled, "U.S. Public Land Survey Monument Record".

Note: A copy of the board-approved form is available from the Department of Regulation and Licensing, Bureau of Business and Design Professions, 1400 East Washington Avenue, P.O. Box 8935, Madison, Wisconsin 53708.

- (3) MONUMENT RECORD REQUIREMENTS. A U.S. public land survey monument record shall show the location of the corner and shall include all of the following elements:
- (a) The identity of the corner, as referenced to the U.S. public land survey system;
- (b) A description of any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence considered by the surveyor, and whether the monument was found or placed;
- (c) Reference ties to at least 4 witness monuments. Witness monuments shall be concrete, natural stone, iron, bearing trees or other equally durable material, except wood other than bearing trees;
- (d) A plan view drawing depicting the relevant monuments and reference ties which is sufficient in detail to enable accurate relocation of the corner monument if the corner monument is disturbed;
- (e) A description of any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished;
- (f) Whether the corner was restored through acceptance of an obliterated evidence location or a found perpetuated location;
- (g) Whether the corner was reestablished through lost-corner-proportionate methods;
- (h) The directions and distances to other public land survey corners which were used as evidence or used for proportioning in determining the corner location; and,
- (i) The stamp and signature or seal and signature of the land surveyor under whose direction and control the corner location was determined and a statement certifying that the U.S. public land survey monument record is correct and complete to the best of his or her knowledge and belief.

History: Cr. Register. February, 1987. No. 374, eff. 3-1-87; am. (1) and (3) (c), Register. May, 1989, No. 401, eff. 6-1-89