

CERTIFIED LAND CORNER RESTORATION

Index No. A-3

State of Wisconsin }
County of LANGLADE } ss.

I RAYMOND S. HALLISY, do hereby certify that on the 7TH day of MAY, 1988, I found evidence of the 44 corner of 31 & 6 Township 32 & 33, North, Range 11E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:


.....
.....
.....

History of original corner establishment:

CORNER SET IN THE 1930 RESURVEY

Description of corner evidence found:


4" IRON PIPE WITH BRASS CAP
AS WITNESS CORNER



Description of monument and accessories I established to perpetuate the original location of this corner.

NEW BT'S TO WITNESS CORNER

12" HARD MAPLE N61W 24'
8" BASSWOOD N26W 35'
8" WHITE BIRCH N11E 38' 7"
4" HARD MAPLE N33E 36' 1"



○ = Corner monument restored.

Dated at Antigo, Wis., this 7TH day of MAY, 1988

Signature Raymond S. Hallisy Title SURVEYOR Registration No. 5-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19..... at..... o'clock..... M.

.....
(Register of Deeds)

By..... Deputy