State	Ωf	Wisconsin	
State	O1	VVISCONSIN	ı

County of .. Langlade --

I Faymond J. Halisv ....., do hereby certify that on the 16th day of Sertember , 19 84 , I found evidence of the Section corner of 1,2,11, 12 ....., North, Range Township.... 12F Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Acsident	witnesses:			
	_			
•••••		•••••		•
•••••				••••••
		***************************************	***************************************	

132NR12E			
,			 
	//		/2
	   	- <b></b>	

O = Corner monument restored.

History of original corner establishment:

1730 resurvey.

Description of corner evidence found:

4" iron size with brass cap bent over by logging equipment, also all XXXXXXXXX ET's destroyed in logging operation.

Description of monument and accessories I established to perpetuate the original location of this corner.

Reset bris cap monument and drove a 7' plastic feace XXXXX post alongside. Mo trees are nearby for ET's.




Dated at mtigo	, Wis.; this	, 16th	day of	Septembe	r	., 1984
Signature (County Surveyor, Register of Deeds, County of instrument was filed in this office for r	My Title	Land Surv	eyor		Registration No.	s-685
(County Surveyor, Regist	tered Land Surv	eyor, or other d	uly authorized	official)		
Office of Register of Deeds, County of	·		•••••	, I' he	reby certify that	the within
instrument was filed in this office for r	ecord on the		day	of	*************	, 19
at			-			-

(Register of Deeds)

SS. County of LANGLADE.

I THOMAS R. ARNOTT , do hereby certify that on the 26<sup>TH</sup> day of MAY , 19.73 , I found evidence of the SECTION corner of SEC3. 1, 2, 11 & 12 Township 33 , North, Range 12 EAST Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident	witnesses:	
		***************************************
••••••		••••••




O = Corner monument restored.

History of original corner establishment:

CERTIFIED LAND CORNER RESTORATION

Description of corner evidence found:

FOUND 1/2" PIPE



Index No. E -21

Description of monument and accessories I established to perpetuate the original location of this corner.

SET Z" IRON PIPE W| BRASS CAP MKD.

1= MAPLE GN 24E 8.7 Z= BALSAM 8S 37E 13.6 3= MAPLE 4 S71W 25.7 4= MAPLE 5 N 45W 16.6 £3°



2 F3. ALL TREES BLAZED & SCRIBED BT

Dated at ANTIGO , Wis., this 13	day of しいと	19.73
Signature how Pitle REG. (County Surveyor, Registered Land Surveyor, or o	LAND SURVEYOR RE	egistration No.S-887
(County Surveyor, Registered Land Surveyor, or o	other duly authorized omciai)	
Office of Register of Deeds, County of	I hereb	y certify that the within
instrument was filed in this office for record on the		
ato'clock	• .	•
	maren 7	e loss .
(Register of Deeds)	County 8	) 
	esimer, o	magn