State of Wisconsin

County of LANGLADE

as described hereon to perpetuate the original

Resident	witnesses:

T33N-R12E				
	!	1		
	1 I	1		
	¦	+ 1		
	1 i 1 1	1		
		<u>+</u>		
		1		
	¦ •	<u> </u>		
	l į l į	I I		
		1		


O = Corner monument restored.

CERTIFIED LAND CORNER RESTORATION

Index No. D-7

History of original corner establishment:

Description of corner evidence found:



SET S'8 COR ON N-S 4 LINE BY PROPORTIONAL MEASUREMENT BETWEEN
CENTER 4 COR AND 5 4 COR. PLACED 14"+42"I.P. W/BRASS CAP AND REFERENCED,
W/Z BT; AND POWER POLE AND E OF ROAD

Description of monument and accessories I established to perpetuate the original location of this corner.

6'18 COP N-S 14 LINE SEC 5 + T33N R 12E 2-15-79 WF 14	POWER POLE L-41	7"N. PINS	PK NAIL I CROSS
Dated at ELCHO			FEBRUARY , 1979
Signature William & (County Survey	Velly Title Co. Me vor, Registered Land Surveyor, or o	NTY SURVEYOR other duly authorized officia	Registration No. S-1098
Office of Register of Deeds, Coinstrument was filed in this off ato'clock	fice for record on the	day of	, I hereby certify that the within
(Regis	ster of Deeds)		