State of Wisconsin County of LANGLADE	ss. H
certify that on the 16 14 of FEBRUARY 19.79 evidence of the SENTER 14 corner of SECTION 5 Nor 12 E Fourth Principal as described hereon; and that from this I established a new monument and as described hereon to perpetuate the location of this corner.	day, I found th, Range Meridian, s evidence Daccessories
Resident witnesses:	
	······
	D
T33N RIZE	
5	D
	Si
	in at
O = Corner monument restored.	В

CERTIFIED	LAND	CORNER	RESTORA	MOITA

History of original corner establishment:

WILLIAM F.

KELLY

S1098

ELCHO,

WIS.

Index No. C-7

Description of corner evidence found:

CENTER "4 COR. SET BY SPLITTING THE DISTANCE BETWEEN THE WEST "4 COR. & THE EAST "4 COR.

Description of monument and accessories I established to perpetuate the original location of this corner.

CENTER 4 C Z"X 4Z" I.R. BRASS CAF CENT. SEC. SEC. S T33N - RIZE Z-16-79 W. F. K. Q"X 4" CEDAR 4' SOUTH OF BRASS CAR	WITH AND STORES	RASS CAP	S CEDAR POST	PK. NAIL IN CROSS
Dated at ELCHO	, Wis., this	day of FL	EBRUARY	, 19. <i>7</i> 2
Signature William Jr. Pell (County Surveyor, Regis	Title			on No. 5-7098
Office of Register of Deeds, County of instrument was filed in this office for	frecord on the	day of	, I hereby certify	/ that the within , 19
ato'clock				
(Register of De	eeds)	<u>.</u>		

PUBLIC LAND SURVEY MONUMENT RECORD U.S.

INSTRUCTIONS:

This record shall show the location of the corner and shall include all of the following nine elements (a through i).


Identify the corner by · (a) reference to the U.S. public land survey system.

O = Corner monument restored.

ORIGINAL CORNER ESTABLISHED BY JAMES NOWLIN IN MAY 1865

TARNOTT RESET CORNER IN 1970'S CORNER USED TO TIE IN "WOLF RIVER HEIGHTS" SUB DIV. BY W. KRLLY

M. SEYMOUR CIRGO) EST. CENTER OF SECT BY INTERSECTING 1/4 LINES



N


Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

M. SEYMOUR EST. CENTER 1/4 CORNER, MARKED WITHERS TREES, THED
10 ARMOTTS CORNER. COUNTY MODUMENT SET

In the plan view drawing below, provide reference ties to at least 4 witness monuments, or, if the location is within a (c) municipality, to at least 2 witness monuments. (Witness monuments shall be made of concrete, natural stone, iron or other equally durable material.) Describe witness monuments.

(d) Show a plan view drawing depicting the relevant monuments and reference ties which is sufficient in detail to enable accurate relocation of the corner monument if the corner monument is disturbed. Indicate north.

c 1/4



Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

SEE SKETCH

- (f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location.?
- (g & h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location.

SEE ATTACHED SKETCH

(1) 1, WILLIAM F. KELLY RLS 1098

(type or print name)

certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Millians Fr. Kelly 5-30-90
Signature Date

