

CERTIFIED LAND CORNER RESTORATION


Index No. C-3

State of Wisconsin }
County of LANGLADE } ss.

History of original corner establishment:

I WILLIAM F. KELLY, do hereby certify that on the 3rd day of APRIL, 1979, I found evidence of the CENTER 1/4 corner of SECT. 6 Township 33, North, Range 12 E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Description of corner evidence found:
LOCATED IRON ROD IN ROAD
SET R.R. SPIKE OVER ROD
AND WIT. CORNER





W. F. Kelly

Resident witnesses:

H. MEISTER

Description of monument and accessories I established to perpetuate the original location of this corner.



Dated at ELCHO, Wis., this 3rd day of APRIL, 1979.

Signature William F. Kelly Title COUNTY SURVEYOR Registration No. S-1098
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy

○ = Corner monument restored.