

CERTIFIED LAND CORNER RESTORATION

Index No. J-3

State of Wisconsin }
County of LANGLADE } ss.


I RAYMOND J. HALLISY, do hereby certify that on the 28th day of MARCH, 1981, I found evidence of the NORTH 1/4 corner of SECTION 18 Township 33, North, Range 12E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:
.....
.....
.....

History of original corner establishment:

ESTABLISHED IN 1939 RESURVEY


Description of corner evidence found:
4" IRON PIPE WITH BRASS CAP
ROCK MOUND



Description of monument and accessories I established to perpetuate the original location of this corner.

NEW BT,S
11" SPRUCE S26W 39'
9" ASPEN N16W 23' 4"
4" RED MAPLE N57E 12' 6"

FORM 985 R. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

Dated at ANTIGO, Wis., this 28th day of MARCH, 1981.

Signature Raymond J. Hallisy REGISTERED LAND SURVEYOR Registration No. 5685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19..... at..... o'clock..... M.

(Register of Deeds)

By..... Deputy