U.S. PUBLIC LAND SURVEY MONUMENT RECORD (Prepared and as required by S. A-E 7.08 W Administrative Code)

The.	M_C_	corner of Sect	ion. <u> 14 </u>	3 N., R. 12 E.,	Langlade County, Wi	
X	(Show bearings Restored/recovere	that apply) acceptance of an obliterate acceptance of a found perp lost and re—established the and distances to PLSS core d/reestablished in a locatio tion. (Show difference in ple	ners used for propo n that differs from	rtioning.)	33/2110022	,
Desc	Check here if add	tional information is shown ce, recovered physical evide	on the reverse side		evidence and all other evi	denc
OR WE	IGINAL - JAN	very/restoration of the com NES L. NOLIN - 186 CORNER SECTION	5- SET WIT	E = 35,70 CHAI	INS TO SW CORNE	
ROE Bur	BERT J. POSS	2 N50W 351ks., - 1968 - FOUND AND ROTTED AWAY	SQUARED ST	TAKE IN MA	RSH-BOG, STAKE	
DE 1 50 AB	AN A WILLI EAST IN OUT 4' INT	AMS 2001-FOUN! LAKE, FOUND 1.C O LAKE, ACCEP1	D B.C.I.P. WIT. DOWN VER ED AS BES	MON. IN COIRTICAL ROTTE TEVIDENCE	YC. SEARCHED FD WOOD IN LAKE OF ORIG. LOCATIO	≡,) / √.
SE	ical description of T ("×60" BARS.	BLACK IRON P	IPE AND 4	NEW TIE	s:3/4" x 30"	
acce	cribe the accessories found/set. in future recovery	es used to perpetuate the Describe measuring point of the corner.	location of the corr on bearing trees.	ner. Include a plan Show any topograp	view drawing and indicate hic features that would NO SCALE	
		- /q	-BANK	LIŢTL	BEARINGS	
			Z. (2)	LAKE	TRAVERSE	
		N68°(2	13 / S		-((2)
	⊗-	N89°58'27"W	32 cs i	DOCK		•
	WIT. B.C.1 IN C	. P. (0. 38.41) ONC. LOY	۸ ا	I"×60" BLACK I'ABOVE WATE		
		AND BO		YORS SEAL	The MC 11 corner of Section 14	
			11		т. 33 м. в. 12 ғ.	INDEX No.
cor by U.S	ner location shown me or under my o . Public Land Surv	RLS-2468, certify that on this record was determ lirection and control and they Monument Record is corbest of my knowledge and	ined at this sum.	LLIAMS 2468 IMIT LAKE S WIS. LAND SURMINIMAN		<u> </u>
6	Jan Wil		2002 2002	LAND SURTHINITY	O=Location of corner	18-19

Date

Signature

WISCONSIN ADMINISTRATIVE CODE

A-E 7.07 Monuments. The type and position of monuments to be set on any survey shall be determined by the nature of the survey, the permanency required, the nature of the terrain, the cadastral features involved, and the availability of maternal. History: Cr. Register, February, 1987, No. 374, eff. 3-1-87

A-E 7.08 U.S. public land survey monument record.

(1) WHEN MONUMENT RECORD REQUIRED. A U.S. public land survey monument shall be prepared and filed with the county surveyor's office as part of any land survey which includes or requires the perpetuation, restoration, reestablishment or use of a U.S. public land survey corner, and,

- (a) There is no U.S. public land survey monument record for the corner on file in the office of the county surveyor or the register of deeds for the county in which the corner is located; or,
- (b) The land surveyor who performs the survey accepts a location for the U.S. public land survey corner which differs from that shown on a U.S. public land survey monument record filed in the office of the county surveyor or register of deeds for the county in which the corner is located, or,
- (c) The witness ties or U.S. public land survey monument referenced in an existing U.S. public land survey monument record have been destroyed or disturbed.
- (2) FORM REQUIRED. A U.S. public land survey monument record shall be prepared on the board-approved form or on a form substantially the same as the board-approved form which includes all the elements required by this section. A form used for this purpose shall be entitled, "U.S. Public Land Survey Monument Record".

Note: A copy of the board-approved form is available from the Department of Regulation and Licensing, Bureau of Business and Design Professions, 1400 East Washington Avenue, P.O. Box 8935, Madison, Wisconsin 53708.

- (3) MONUMENT RECORD REQUIREMENTS. A U.S. public land survey monument record shall show the location of the corner and shall include all of the following elements:
- (a) The identity of the corner, as referenced to the U.S. public land survey system;
- (b) A description of any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence considered by the surveyor, and whether the monument was found or placed;
- (c) Reference ties to at least 4 witness monuments. Witness monuments shall be concrete, natural stone, iron, bearing trees or other equally durable material, except wood other than bearing trees;
- (d) A plan view drawing depicting the relevant monuments and reference uses which is sufficient in detail to enable accurate relocation of the corner monument if the corner monument is disturbed:
- (e) A description of any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished;
- (f) Whether the corner was restored through acceptance of an obliterated evidence location or a found perpetuated location;
- (g) Whether the corner was reestablished through lost-corner-proportionate methods;
- (h) The directions and distances to other public land survey corners which were used as evidence or used for proportioning in determining the corner location; and,
- (i) The stamp and signature or seal and signature of the land surveyor under whose direction and control the corner location was determined and a statement certifying that the U.S. public land survey monument record is correct and complete to the best of his or her knowledge and belief.

History: Cr. Register, February, 1987, No. 374, eff. 3-1-87, am. (1) and (3) (c), Register, May, 1989, No. 401, eff. 6-1-89.

N86°15'57W (2601.35)

SW COR.

BEARING CHANGE

585°56'32"E

300.92' | S85°56'32"E

MC '/4 COR IN 2611.13

OF LAKE

W/4 (Witness 1/4)

SE COR.

State	e of W	isco	nsin	\ .sc
County of	LANG	9LA	0E	J 33.
I. Los	set J	1 /) ఇక్క	
certify that	on the	20	74	
of	ME.		, 19	68 , I for
evidence of corner of				
Township	<u></u> 33^	/	:/T	North Rai
MEA:	57,	Fourt	h, Princ	cipal Meridi
as described	hereon;	and th	at fron	this evide
I establishe				
as described			rpetuat	te the origi
location of	this corn	er.		
				•
	ī .	ı		<u> </u>
}	i t	1		1
	i	ı		!
	•			i
L	16	5 <i>€</i> c.		. <u>l</u>
	- 4	\$ <u>€</u> c.	<u> </u>	·
	5	≶€C. 	<u> </u>	
	1 6 	SEC. - -		
	1 6	5 <u>ec.</u> 	!/	

O = Corner monument restored.

CERTIFIED LAND CORNER RESTORATION
History of original corner establishment:
ROBERT
POSS S-0001 ELCHO. WISCORSIN
Description of corner evidence found:
FOUND SQUARED STAKE IN THAREH - BOG. STAKE BURNED AT TOP & ROTTED AWAY.

Description of monument and accessories I established to perpetuate the original location of this corner.

BRS ARE MAG	SET WITNESS 1= W. BIRCH 14 NG 4 W 2- LINDEN IN CLUMP SEA 3= MAPLE 8 S 23/2 W 18 4: MAPLE 6 S 86 1/2 W 2	7",	100 of 10	0 < 50 × 50 × E	٠ لا	BRASS CAP IN CONC. MON MKD, WIT. COR SEC II 36C.14 EAST 50.0F T
4	LL TREES BLAZED & SCI	eiBED NBT.	21 57	day of	JUNE	, 19. 68
Signa	ture(County Surveyor	Title K	EG. LAND or, or other duly a	SURVEYO. authorized official	R Regis	stration No. 5- /
instru	of Register of Deeds, Coument was filed in this offic	e for record on the				
•	(Registe	r of Deeds)	·			
Βv			Denuty			