

CERTIFIED LAND CORNER RESTORATION

33-12

Index No. G-23

State of Wisconsin }
County of Langlade } ss.

I, Raymond J. Hallisy, do hereby certify that on the 5th day of July, 19 71, I found evidence of the Center $\frac{1}{4}$ corner of Section 12 Township 33, North, Range 12E, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Corner set by M. Hutchinson

Description of corner evidence found:

Found iron pipe and parts of wood stake

Resident witnesses:

.....
.....
.....


Description of monument and accessories I established to perpetuate the original location of this corner.

Set 2" pipe with brass cap $1\frac{1}{2}$ " pipe alongside, rock mound

BT's to corner
Hard Maple 8" S17E 19 Feet 7 inches
Hard Maple 7" N 12E 13 Feet 10 inches
BT's faced at base of tree and scribed BT



FORM 985 H. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

Dated at Antigo, Wis., this 5th day of July, 19 71

Signature R. J. Hallisy Title Reg. Land Surveyor Registration No. 685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of....., I hereby certify that the within instrument was filed in this office for record on the.....day of....., 19..... at.....o'clock..... M.

.....
(Register of Deeds)

By.....Deputy