

CERTIFIED LAND CORNER RESTORATION

33-11

Index No. M-1

State of Wisconsin }
County of Lengle } ss.

History of original corner establishment:

33-12

Corner Set in The 1930 resurvey

I Raymond T. Hallisy do hereby certify that on the 11th day of November, 1972, I found evidence of the S 1/4 corner of Sec 13 + 18 Township 33, North, Range 11 + 12 E, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.



Description of corner evidence found:

Wood Corner Standing in N. Edge of Swamp

Resident witnesses:

Description of monument and accessories I established to perpetuate the original location of this corner.

Set 1 1/2" iron pipe with brass cap
New BT's
Spruce 4" N62W 7FT 11 in.
Spruce 4" S50E 13FT 11 in.



○ = Corner monument restored.

Dated at Antigo, Wis., this 11th day of November, 1972

Signature [Signature] Title R.T.D. Registration No. 10068
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy

FORM 985 R. C. MILLER CO., MILWAUKEE