

CERTIFIED LAND CORNER RESTORATION

Index No. N-5

33-12

State of Wisconsin }  
County of Lan glade } ss.

I Raymond J. Hallisy, do hereby certify that on the 22nd day of July, 1979, I found evidence of the Section corner of 17, 18, 19, & 20 Township 33, North, Range 12E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

History of original corner establishment:

Corner set in the 1930 resurvey.

Description of corner evidence found:

4" pipe with brass cap, rock mound.



Resident witnesses:

.....  
.....  
.....

Description of monument and accessories I established to perpetuate the original location of this corner.

New BT's

7"	Red Maple	N51E	26'	8"
7"	Spruce	N89E	25'	11"
4"	Cherry	S10E	5'	8"
5"	Spruce	S1E	17'	7"



○ = Corner monument restored.

Dated at Antigo, Wis., this 22nd day of July, 1979.

Signature Raymond J. Hallisy Title Reg. Surveyor Registration No. S685  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of \_\_\_\_\_, I hereby certify that the within instrument was filed in this office for record on the \_\_\_\_\_ day of \_\_\_\_\_, 19\_\_\_\_ at \_\_\_\_\_ o'clock \_\_\_\_\_ M.

.....  
(Register of Deeds)

By \_\_\_\_\_ Deputy

FORM 985 W. C. MILLER CO., MILWAUKEE