

CERTIFIED LAND CORNER RESTORATION

Index No. N-3

33-12

State of Wisconsin }
County of Langelo } ss.

I Raymond J. Hallisy, do hereby certify that on the 21st day of July, 1979, I found evidence of the 1/4 corner of Section 18 & 19 Township 33, North, Range 12E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

.....
.....
.....

History of original corner establishment:

Corner set in the 1930 resurvey.



Description of corner evidence found:

4" pipe with brass cap
36" pine stump N44W 10' 3"
Location poster on small aspen N44W 5' 6"

Description of monument and accessories I established to perpetuate the original location of this corner.

New BT's

9" Cherry N48E 36' 11"
10" Aspen S15E 31' 3"



○ = Corner monument restored.

Dated at Antigo, Wis., this 21st day of July, 1979

Signature Raymond J. Hallisy Title Reg. Surveyor Registration No. S685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19..... at..... o'clock..... M.

.....
(Register of Deeds)

By..... Deputy

FORM 985 H. C. MILLER CO., MILWAUKEE