State of Wisconsin

O = Corner	monument	restored.
------------	----------	-----------

CERTIFIED LAND CORNER RESTORATION

33-12

History of original corner establishment:

Corner set in the 1930 resurvey.

Description of corner evidence found:

Wood post down, marks faint, point intact.

Description of monument and accessories I established to perpetuate the original location of this corner.

Set 2" pipe with brass cap. New BT's

21 611 S71W Aspen **S86E** 30' 1" Hard Maple 331 611 N25E Basswood



Dated at Antigo	, Wis., this	?lst	day of	July	, 19. 79
Dated at Antigo Signature (County Surveyor,	llify Title	Reg. Su	rveyor		Registration No5685
(County Surveyor,	Registered Land Surve	yor, or other o	duly authorized o	official)	_
Office of Register of Deeds, Coun	ty of			I h	ereby certify that the within
instrument was filed in this office	for record on the		day	of	, 19
at o'clock M.					
		. 			
(Register	of Deeds)				