

CERTIFIED LAND CORNER RESTORATION

Index No. 2-001

33-12

State of Wisconsin }
County of LANGLADE } ss.

I RAYMOND J. HALLISY, do hereby certify that on the 22nd day of MARCH, 1921, I found evidence of the 1/4 corner of SECTION 13 Township 33, North, Range 11 E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:


.....
.....
.....

History of original corner establishment:

ESTABLISHED IN 1936 RESURVEY

Description of corner evidence found:


4" IRON PIPE WITH BRASS CAP
B.C.
STONE WITH x N14E 7' 2"
STONE WITH + S87W 20' 10"



Description of monument and accessories I established to perpetuate the original location of this corner.

NEW B.T.S

8" BASSWOOD N12W 11' 2"
8" HARD MAPLE S5W 31' 1"
8" BASSWOOD S66W 35'



○ = Corner monument restored.

Dated at ANTIGO, Wis., this 22nd day of MARCH, 1921.

Signature Raymond J. Hallisy REGISTERED LAND SURVEYOR Registration No. 5685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of, I hereby certify that the within instrument was filed in this office for record on the day of, 19..... at o'clock M.

(Register of Deeds)

By Deputy

FORM 985 H. C. MILLER CO., MILWAUKEE