

CERTIFIED LAND CORNER RESTORATION

SB-12

Index No. R-16

State of Wisconsin }  
County of LANGLADE } ss.

History of original corner establishment:

CORNER SET IN 1930'S UNDER A COUNTY RESURVEY PROJECT

I RAYMOND HALLISY, do hereby certify that on the 10 day of MAY, 1969, I found evidence of the E 1/16 corner of T 33N Township, North, Range 12E, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Description of corner evidence found:

SQUARE POST SCRIBED E 1/16 - 522 AND 527

Resident witnesses:

GERALD WEIX

JERRY KRYKA

Description of monument and accessories I established to perpetuate the original location of this corner.

SET 2 INCH IRON PIPE WITH BRASS CAP AND ROCK MOUND

MARKED

BEARING TREES MARKED WITH B. T.

T 33N R 12E

SEC 22

SEC 27

E 1/16

YELLOW BIRCH 8" N12°W 4' 3"

YELLOW BIRCH 9" S60°E 16' 9"

Dated at ANTIGO, Wis., this 4 day of JUNE, 1969.


Signature Raymond J. Hallisy Title Reg. Land Surveyor Registration No. 5-685  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of \_\_\_\_\_, I hereby certify that the within instrument was filed in this office for record on the \_\_\_\_\_ day of \_\_\_\_\_, 19\_\_\_\_ at \_\_\_\_\_ o'clock \_\_\_\_\_ M.

(Register of Deeds)

By \_\_\_\_\_ Deputy

FORM 985 M. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.