

CERTIFIED LAND CORNER RESTORATION

33-12


Index No. V-22

State of Wisconsin }
County of Langlade } ss.

I Raymond J. Hallisy, do hereby certify that on the 4th day of May, 19 69, I found evidence of the W 1/16 corner of Section 25 Township 33, North, Range 12E, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

.....
.....
.....



○ = Corner monument restored.

History of original corner establishment:

Corner set in the 1930 resurvey

Description of corner evidence found:

Found old stake standing marked W 1/16

Description of monument and accessories I established to perpetuate the original location of this corner.

Set 2" pipe with brass cap and rock mound.
B.T.'s to corner
Hard maple 7" 90E 1Ft. 6 inches
Basswood 10" S34W 6Ft. 3 inches
BT's faced and scribed BT



Brass Cap Marked

Dated at Antigo, Wis., this 4th day of May, 19 69

Signature Raymond J. Hallisy Title Reg. Land Surveyor Registration No. S-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19 _____ at _____ o'clock _____ M.

.....
(Register of Deeds)

By _____ Deputy