

CERTIFIED LAND CORNER RESTORATION

Index No. V-11

State of Wisconsin }  
County of Lançlade } ss.

I Raymond J. Hallisy, do hereby certify that on the 13th day of November, 19 82, I found evidence of the 1/4 corner of Section 28 & 33 Township 33, North, Range 12E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:


.....  
.....  
.....

History of original corner establishment:

Corner set in the 1930 resurvey.

Description of corner evidence found:

~~4"~~ 4" pipe with brass cap, rock mound.




Description of monument and accessories I established to perpetuate the original location of this corner.

New BT's

6" Aspen N26W 23.7'  
7" Aspen N52E 22.8'  
8" Aspen S69E 32.5'

FORM 985 M. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

Dated at Antigo, Wis., this 13th day of November, 19 82.

Signature Raymond J. Hallisy Title Land Surveyor Registration No. S-685  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19..... at..... o'clock..... M.

.....  
(Register of Deeds)

By..... Deputy