

CERTIFIED LAND CORNER RESTORATION

33-12

Index No. S-13


State of Wisconsin }
County of LANGLADE } ss.

I RAYMOND HALLISY, do hereby certify that on the 10 day of MAY, 1969, I found evidence of the N 1/16 corner of 27 Township 33N, North, Range 12E, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

GERALD WEIX

JERRY KRYKA



○ = Corner monument restored.

History of original corner establishment:

CORNER SET IN 1930'S UNDER A COUNTY RESURVEY PROJECT

Description of corner evidence found:

SQUARE POST SCRIBED: N 1/16 - Sec 28 AND Sec 27

ALSO 6 FOOT 1/4" IRON PIPE BESIDE THE POST

Description of monument and accessories I established to perpetuate the original location of this corner.

SET 2" IRON PIPE WITH BRASS CAP AND ROCK MOUND

MARKED

BEARING TREES MARKED B.T.

T 33N R 12E

Sec | Sec
28 | 27

N 1/16

ELM 11" S2°E 44' 2"

ELM 7" N36°W 41' 9"

Dated at ANTIGO, Wis., this 4 day of June, 1969.

Signature Raymond J. Hallisy Title Reg. Land Surveyor Registration No. 5-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy

FORM 985 H. C. MILLER CO., MILWAUKEE