

CERTIFIED LAND CORNER RESTORATION

Index No. T-9

State of Wisconsin }
County of Langlade } ss.

I Raymond J. Hallisy, do hereby certify that on the 8th day of April, 1978, I found evidence of the W 1/4 corner of Section 28 Township 33, North, Range 12 EAST, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

.....
.....
.....


History of original corner establishment:

Corner Established in 1939 Resurvey

33-11

Description of corner evidence found:


4 inch Brass cap on 4 inch IRON PIPE



Description of monument and accessories I established to perpetuate the original location of this corner.

Cherry 8" N 81° W 16 FT.
Hard Maple 20" S 45° E 24 FT. 4 inches
Hard Maple 12" S 14° W 37 FT. 4 inches

FORM 985 H. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

Dated at Antigo, Wis., this 8th day of April, 1978.

Signature Raymond J. Hallisy Title Registered Land Surveyor Registration No. 5-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

.....
(Register of Deeds)

By _____ Deputy