

CERTIFIED LAND CORNER RESTORATION

Index No. V-5

33-12

State of Wisconsin }
County of Langlade } ss.

I Raymond J. Hallisy, do hereby certify that on the 8th day of April, 1978, I found evidence of the SECTION corner of 29, 30, 31, 32 Township 33, North, Range 12 EAST, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:


.....
.....
.....

History of original corner establishment:

Corner Established in 1939 Resurvey

Description of corner evidence found:

4 inch IRON PIPE WITH BRASS CAP




Description of monument and accessories I established to perpetuate the original location of this corner.

New B.T.s

- Hemlock 7" N82°E 14 FT 10 inches
- Basswood 7" S35°E 17 FT.
- CHERRY 10" N49°E 22 FT. 2 inches
- Hemlock 16" N27°W 24 FT. 4 inches

FORM 985 H. C. MILLER CO., MILWAUKEE

T 33 N R 12 E



○ = Corner monument restored.

Dated at Antigo, Wis., this 8th day of April, 1978.

Signature Raymond J. Hallisy Title Registered Land Surveyor Registration No. S-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of, I hereby certify that the within instrument was filed in this office for record on the day of, 19..... at o'clock M.

.....
(Register of Deeds)

By..... Deputy