

CERTIFIED LAND CORNER RESTORATION

33-12

Index No. V-2

State of Wisconsin }  
County of Langlade } ss.

I Raymond J. Hallisy, do hereby certify that on the 4th day of May, 1969, I found evidence of the W 1/16 corner of Section 30 Township 33, North, Range 12E, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

History of original corner establishment:

Corner set in the 1930 resurvey.

Description of corner evidence found:

Found old stake standing and rock mound. corner in E & W fence  
Marked W1/16 S30 S31

Resident witnesses:


.....  
.....  
.....

Description of monument and accessories I established to perpetuate the original location of this corner.

Set 1 1/4" pipe with a 4" brass cap and rock mound.  
B.T.'s to corner  
Elm 5" N85W 29Ft. 3 inches  
Elm 5" N28E 22Ft. 10 inches  
B.T.'s faced at base and scribed BT



Brass CAP MARKED



○ = Corner monument restored.

Dated at Antigo, Wis., this 4th day of May, 1969.

Signature Raymond J. Hallisy Title Reg. Land Surveyor Registration No. S-685  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of....., I hereby certify that the within instrument was filed in this office for record on the.....day of....., 19..... at.....o'clock..... M.

(Register of Deeds)

By.....Deputy

FORM 985 M. C. MILLER CO., MILWAUKEE