

CERTIFIED LAND CORNER RESTORATION

32-12
Index No. A-9

State of Wisconsin }
County of LANGLADE } ss.

I, RAYMOND HALLISY, do hereby certify that on the 26 day of APRIL, 19 69, I found evidence of the Nor West SEC COR corner of SEC 4 Township 32, North, Range 12E, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

.....
.....
.....

History of original corner establishment:

CORNER SET IN 1930'S UNDER A COUNTY RESURVEY PROJECT

Description of corner evidence found:


FOUND A 1 1/4" IRON PIPE WITNESS CORNER - LOCATED 50 LKS EAST OF CORNER LOCATED IN CTH "5"

Description of monument and accessories I established to perpetuate the original location of this corner.

SET NINCH BRASS CAP SET IN PIPE WITH CONCRETE

MARKED

BEARING TREES MARKED WITH "B.T."



HARD MAPLE 6" N38°E 19'
ELM 8" S64°E 11'9"

Dated at ANTIGO, Wis., this 4 day of JUNE, 19 69

Signature Raymond J. Hallisy Title Reg. Land Surveyor Registration No. S-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19 _____ at _____ o'clock _____ M.

.....
(Register of Deeds)

By _____ Deputy

FORM 985 H. C. MILLER CO., MILWAUKEE

○ = Corner monument restored.