

CERTIFIED LAND CORNER RESTORATION

Index No. A+ 16

State of Wisconsin }  
County of Langlade } ss.

I Raymond Hallisy, do hereby certify that on the 3rd day of July, 1987, I found evidence of the E 1/16 corner bet section 3 & 34 Township 33, 32, North, Range 12 E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

.....  
.....  
.....

History of original corner establishment:

Corner set in 1939s Resurvey

Description of corner evidence found:



Squared wood post in Rockmound  
scribed 532, 53, E 1/16

Description of monument and accessories I established to perpetuate the original location of this corner.

New BTs

set 3" aluminum pipe with cap

- Hard maple 6" N24°W 7'8"
- " " 6" N24°E 11'8"
- " " 7" N87°E 11'10"
- " " 6" S21°E 15'6"



○ = Corner monument restored.

Dated at Antigo, Wis., this 3rd day of July, 1987.

Signature Raymond Hallisy Title Land Surveyor Registration No. 5-685  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of \_\_\_\_\_, I hereby certify that the within instrument was filed in this office for record on the \_\_\_\_\_ day of \_\_\_\_\_, 19\_\_\_\_ at \_\_\_\_\_ o'clock \_\_\_\_\_ M.

.....  
(Register of Deeds)

By.....Deputy